



NEWPORT NEWS

Photos of Flooding Events



Photo 1: Polluted waterways: *Plastics, food containers, and other polluting debris from the streets flow into the City's Seafood Industrial Park Harbor during storms.*



Photo 2: Flood challenges: A single-family home near Salters Creek experiences street flooding and crawl space inundation during hurricanes and Nor'easters. Despite efforts to enlarge drainage infrastructure, flooding remains an issue during high tides and heavy rains. Source: Fred Rattliff frattliff@gmail.com



Photo 3: Flood challenges: A single-family home near Salters Creek experiences street flooding and crawl space inundation during hurricanes and Nor'easters. Despite efforts to enlarge drainage infrastructure, flooding remains an issue during high tides and heavy rains. Source: Fred Rattliff frattliff@gmail.com



Photo 4: Flood-prone streets: Heavy rains lead to flooding at the lowest point of Belvoir Circle. Residents report worsening conditions and enduring sleepless nights during storms. Source: Muriel Aiken maiken125@cox.net



Photo 5: Flood-prone living: Heavy rains lead to flooding at the lowest point of Belvoir Circle. Residents report worsening conditions and enduring sleepless nights during storms. Source: Muriel Aiken maiken125@cox.net



Photo 6: Flood-prone living: Heavy rains lead to flooding at the lowest point of Belvoir Circle. Residents report worsening conditions and enduring sleepless nights during storms. Source: Muriel Aiken maiken125@cox.net



Photo 7: Reoccurring flooding: A single-family home on Nicewood Drive faces flooding over three times a year, with up to 3 feet of water threatening the property. Residents live with water pooling for 24 hours after heavy rainfalls, showing the urgent need for flood mitigation. Source: B. Clukey bannc19@yahoo.com



Photo 8: Erosion and Water Quality Challenges:

Untreated stormwater outfall leads to extensive beach erosion and James River pollution.



Photo 9: Erosion and Water Quality Challenges:

Chemicals, waste, and debris flow onto the dune and into the James River.



Photo 10: Erosion and Water Quality Challenges:

Another photo of the erosion.

Source: Patrick Wright
patwright45@yahoo.com



Photo 11: Rickneck Rd. [Source: Ed Ellington \(social media\).](#)



Photo 12: Salters Creek. [Source: Michael Carter \(social media\).](#)



Photo 13: Rickneck Road. [Source: Amanda Huff \(social media\).](#)



Photo 14: Salters Creek. Source: Junius Harris ([social media](#)).



Photo 15: Salters Creek. Source: Fred Rattliff (frattliff@gmail.com)